

We use some essential cookies to make this service work.

We'd like to set additional cookies so we can remember your settings, understand how people use the service and make improvements.

Accept additional cookies

Reject additional cookies

View cookies

Check the MOT history of a vehicle

Help us make this service better. Give us your [feedback](#).

< [Back](#)

HYUNDAI I30

[Check another vehicle](#)

Colour

Grey

Fuel type

Petrol

Date registered

18 September 2010

MOT valid until

17 October 2026

[Get an MOT reminder](#) by email or text.

[Download test certificates](#)

You can [get information corrected on your MOT history](#) (such as mileage or vehicle details) if it's wrong.

⌵ Hide all sections

MOT history

Check mileage recorded at test, expiry date, and test outcome

● Hide

Date tested

9 October 2025

PASS

Mileage

74,634 miles

Test location

▶ [View test location](#)

MOT test number

2842 4856 4984

Expiry date

17 October 2026

Monitor and repair if necessary (advisories):

- Front Brake disc worn, pitted or scored, but not seriously weakened Both discs inner faces (1.1.14 (a) (ii))
- Offside Front Tyre worn close to legal limit/worn on edge Bald on edges (5.2.3 (e))
- Nearside rear tyre thin on inner edge.

▶ [What are advisories?](#)

Date tested

9 October 2025

FAIL

Mileage

74,634 miles

Test location

▶ [View test location](#)

MOT test number

2477 6627 6085

Repair immediately (major defects):

- Offside Stop lamp(s) not working (4.3.1 (a) (ii))

Monitor and repair if necessary (advisories):

- Front Brake disc worn, pitted or scored, but not seriously weakened Both discs inner faces (1.1.14 (a) (ii))
- Offside Front Tyre worn close to legal limit/worn on edge Bald on edges (5.2.3 (e))
- Nearside rear tyre thin on inner edge.

▶ [What are defects and advisories?](#)

Date tested

18 October 2025

PASS

Mileage

69,338 miles

Test location

▶ [View test location](#)

MOT test number

6704 5919 1677

Expiry date

17 October 2025

Monitor and repair if necessary (advisories):

- Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Nearside Rear Upper Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Offside Rear Upper Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Rear Exhaust mounting defective Silencer (6.1.2 (a))

▶ [What are advisories?](#)

Date tested

18 October 2024

FAIL

Mileage

69,336 miles

Test location

▶ [View test location](#)

MOT test number

9664 7621 0841

Repair immediately (major defects):

- Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Nearside Headlamp aim unable to be tested (4.1.2 (b))

Repair as soon as possible (minor defects):

- Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Monitor and repair if necessary (advisories):

- Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Nearside Rear Upper Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Offside Rear Upper Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Rear Exhaust mounting defective Silencer (6.1.2 (a))

▶ [What are defects and advisories?](#)

Date tested

24 November 2023

PASS

Mileage

65,060 miles

Test location

▶ [View test location](#)

MOT test number

6283 8513 1049

Expiry date

18 December 2024

Monitor and repair if necessary (advisories):

- Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

▶ [What are advisories?](#)

Date tested

24 November 2023

FAIL

Mileage

65,060 miles

Test location

▶ [View test location](#)

MOT test number

2824 6826 5872

Repair immediately (major defects):

- Nearside Headlamp aim too low (4.1.2 (a))

Monitor and repair if necessary (advisories):

- Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

▶ [What are defects and advisories?](#)

Date tested

19 December 2022

PASS

Mileage

60,485 miles

Test location

▶ [View test location](#)

MOT test number

5540 2450 7547

Expiry date

18 December 2023

Monitor and repair if necessary (advisories):

- slight parking brake travel
- Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Offside Rear Service brake binding but not excessively (1.2.1 (f))
- rear wiper blade det

▶ [What are advisories?](#)

Date tested

21 May 2019

PASS

Mileage

47,212 miles

Test location

▶ [View test location](#)

MOT test number

8857 9511 8545

Expiry date

20 November 2020

Monitor and repair if necessary (advisories):

- Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

▶ [What are advisories?](#)

The MOT test changed on 20 May 2018

Defects are now categorised according to their severity - dangerous, major, and minor. [Find out more](#).

Date tested

24 April 2018

PASS

Mileage

44,615 miles

Test location

▶ [View test location](#)

MOT test number

9181 2432 7889

Expiry date

23 April 2019

Date tested

24 April 2018

FAIL

Mileage

44,615 miles

Test location

▶ [View test location](#)

MOT test number

9718 5396 1403

Reason(s) for failure

- Nearside Headlamp aim too low (1.2.1b)

▶ [What are failures?](#)

Date tested

22 February 2017

FAIL

Mileage

44,581 miles

Test location

▶ [View test location](#)

MOT test number

7809 3316 1260

Reason(s) for failure

- Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Windscreen washer provides insufficient washer liquid (8.2.3)
- Nearside Stop lamp not working (1.2.1b)
- Nearside Headlamp aim too low (1.8)
- Offside Headlamp aim too low (1.8)
- Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g) Dangerous
- Nearside Rear brake disc in such a condition that it is seriously weakened (3.5.1f) Dangerous
- rear brake application uneven (3.7.B.2)

Advisory notice item(s)

- OIL leaking from engine
- Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Offside Front Brake pad(s) wearing thin (3.5.1g)
- Offside Rear Brake pad(s) wearing thin (3.5.1g)

▶ [What are failures and advisories?](#)

Date tested

14 November 2015

PASS

Mileage

39,778 miles

Test location

▶ [View test location](#)

MOT test number

5910 1720 0506

Expiry date

11 December 2016

Advisory notice item(s)

- Rear Brake pad(s) wearing thin (3.5.1g)

▶ [What are advisories?](#)

Date tested

14 November 2015

FAIL

Mileage

39,778 miles

Test location

▶ [View test location](#)

MOT test number

6671 4478 5170

Reason(s) for failure

- Offside Stop lamp not working (1.2.1b)
- Windscreen washer provides insufficient washer liquid (8.2.3)

Advisory notice item(s)

- Rear Brake pad(s) wearing thin (3.5.1g)

▶ [What are failures and advisories?](#)

Date tested

25 November 2014

PASS

Mileage

32,985 miles

Test location

▶ [View test location](#)

MOT test number

4161 7962 4381

Expiry date

11 December 2015

Date tested

25 November 2014

FAIL

Mileage

32,985 miles

Test location

▶ [View test location](#)

MOT test number

9366 1972 4399

Reason(s) for failure

- Nearside Front Headlamp aim too high (1.8)
- Offside Front Headlamp aim too high (1.8)
- Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

▶ [What are failures?](#)

Date tested

12 December 2013

PASS

Mileage

24,436 miles

Test location

▶ [View test location](#)

MOT test number

8964 2634 3380

Expiry date

11 December 2014

Safety recalls

We do not have recall information for this vehicle.

Contact your local HYUNDAI dealership to check if the vehicle has been recalled.